

## Office Building Fan Flies Apart



### LOSS DETAILS:

<b>Nature of Business:</b>	Office Building
<b>Type of Equipment:</b>	Air Handling Fan
<b>Age of Equipment:</b>	10 years old

### FINAL LOSS

<b>Settlement Amount:</b>	\$20,075.00
---------------------------	-------------

At 3:00 a.m. in the morning a loud “bang” was heard from the top floor office area.

Neighbours called the police who in turn called the building superintendent.

Investigation revealed that a 1.5 metre diameter return fan was completely destroyed. Pieces of metal lay all over the fan’s housing chamber.

This type of fan was found to no longer be in supply. A new type was needed and construction adjustments were required to the existing housing. The cause of loss is believed to be metal fatigue.